


Wichtige qualitätsrelevante Informatione Important quality relevant information





'RIC 'RC 'FC tolerance into right → into left 🗸

ATTENTION

Possible longitudinal seam tolerance in bulk production